

INITIAL SEISMIC ASSESSMENT REPORT (ISA PLUS)

Beauty and Beyond

18 Kelvin Street, Invercargill



Client Name: HWCP Management Limited

BMC Reference: 1711-2266

Date Issued: 9/04/2018

Quality Statement and Document Control

This Initial Seismic Assessment report has been prepared for HWCP Management Limited by Batchelar McDougall Consulting Limited. No liability is accepted by this company or any employee or sub-consultant of this company with respect to its use by any other parties.

This disclaimer shall apply notwithstanding that the documents may be made available to other persons for an application for permission or approval to fulfil a legal requirement.

Issue Register:

Revision	Date	Description		
A	9/04/2018	ISA (Plus)		
		Prepared by	Reviewed by	Approved by
	Name	Charlotte Corston	Matt Stewart	Andrew Marriott
	Signature	 Be(hons), MEngNZ	 BSCE (USA-CA), PE (USA-CA), CMEngNZ	 BE, CPEng, CMEngNZ, IntPE(NZ), MICOMOS

Revision History:

Rev. No	Date	Issue Description	Prepared by	Reviewed by

Contents:

1	Executive Summary	3
2	Scope of Our Engagement	4
3	Building Description.....	5
3.1	General Overview.....	5
3.2	Construction Materials & Configuration	6
3.3	Lateral Load Resisting Structural System.....	8
3.4	Foundations & Geotechnical	9
4	Building Inspection	9
4.1	Documentation	9
4.2	Observations and/or Damage	9
5	Assessment.....	12
5.1	Specific Calculations / Engineering Assessment	12
5.2	IEP Spreadsheet Calculations	12
6	Seismic Restraint of Non-Structural Items	13
7	Continued Occupancy Recommendations	13
8	Conclusions.....	13
APPENDIX A - NZSEE IEP Spreadsheet & Out-of-Plane Wall Calculation		A

1 Executive Summary

The following report covers the Initial Seismic Assessment (ISA Plus) of the building at 18 Kelvin Street, Invercargill. This building has “Tier 2” heritage status in the “Proposed Invercargill City District Plan”, dated January 2017.

The two-storey building that is constructed of unreinforced masonry (URM) perimeter walls and timber floor/roofing framing. It was constructed circa 1910. The building is located in the Invercargill CBD which is identified as having a ‘medium’ seismic risk with a seismic hazard factor of 0.17. For comparison, Christchurch has a seismic hazard design value of 0.3 and is labelled as ‘high’ seismic risk, while Dunedin has a seismic hazard value of 0.13 and is labelled as ‘low’ seismic risk.

Documentation available to Batchelar McDougall Consultants Limited (BMC) for the purposes of this assessment is summarised in Section 4.1. This assessment is based on these documents and site visit observations only.

For the purposes of this evaluation, the building has been assessed as a structure of Importance Level 2 (IL2) – Normal Building.

BMC have completed an NZSEE Initial Evaluation Procedure (IEP) spreadsheet. In addition, BMC has provided an initial assessment of the building and carried out a calculation of the out-of-plane performance of a critical wall.

From this assessment, the building is considered to have a lateral load carrying capacity of 15-20 % New Building Standard (%NBS) for an IL2 building as follows,

Loading direction	Building %NBS (IL2)	Seismic Grade	Limiting performance
North-South (Longitudinal)	15-20% NBS	E	Out-of-plane capacity storefront wall (north wall facing Kelvin Street) and rear URM walls
East-West (Transverse)	15-20% NBS	E	In-plane soft storey at the storefront and out-of-plane horizontal off-set of rear URM walls

Refer to Section 5 for explanation and summary of assessment.

A ‘Desk Top’ geotechnical assessment from nearby sites has been referenced in relation to likely geotechnical conditions for this site. The building is assumed to have shallow strip footing foundations which will likely be subject to some differential settlement as a result of liquefaction under a significant (ULS) seismic event.

Our ISA Plus found that the building at 18 Kelvin Street, Invercargill has a capacity less than 34%NBS (IL2), and the building, therefore, is considered to be potentially Earthquake Prone as defined in the Building Act.

Note the ISA Plus is considered to provide a relatively quick, high-level and mostly qualitative measure of the building's performance. If a more defined level of performance is required then a Detailed Seismic Assessment (DSA) would need to be carried out.

2 Scope of Our Engagement

As requested by HWCP Management Limited, Batchelar McDougall Consulting Limited (BMC) has undertaken a comprehensive Initial Seismic Assessment (ISA Plus) of the seismic capacity of the building at the above noted address.

The seismic assessment and reporting have been undertaken in accordance with the qualitative procedures detailed in "The Seismic Assessment of Existing Buildings, Technical Guidelines for Engineering Assessments" issued by the Ministry of Business, Innovation and Employment (MBIE) and now cited in the Building (Earthquake-prone buildings) Amendment Act 2016 (which has now been integrated into the Building Act 2004) with reference to potentially earthquake prone buildings. BMC have included a simple calculation / assessment of an element of the building form(s) or structure(s) that BMC have assessed as limiting the global seismic capacity of the building.

This structural assessment includes:

- Review of existing building plans or production of a scale layout plan and review of any prior reports, if available.
- Undertaking interior and exterior visual inspection of exposed elements on-site, where access is available.
- Consideration of the general established geotechnical evidence for the site (from the initial 'Desktop Study' relevant to the CBD block by Geosolve Limited).
- Completion of an Initial Evaluation Procedure (IEP) spreadsheet(s).
- Engineering assessment and/or calculation of a primary or critical structural element that is considered to limit the global seismic capacity of the building.
- Production of a summary report.

The assessment is made with regard to Clause B1 – Structure of the New Zealand Building Code. No other Building Code Clauses have been assessed by this report.

This structural assessment is based on the visual evidence and indications present at the time of inspection. No specific invasive investigation work has been carried out (although wall thicknesses and wall/parapet heights may be determined). The findings of this report may therefore be subject to revision pending further and more detailed investigation or assessment and/or deterioration of elements from earthquake or ground settlement. This report does not address any hidden or latent defects that may have been incorporated in the original design and construction.

This assessment has been restricted to structural aspects only. Waterproofing elements, electrical and mechanical equipment, fire protection and safety systems, service connections, water supplies and sanitary fittings have not been reviewed, and secondary elements such as internal fit out have not been reviewed.

The scope of this evaluation is limited to the initial or first stage assessment of the potential performance of the building in an earthquake ONLY. No assessment has been made of other load cases such as wind, snow and gravity.

BMC's professional services are performed using a degree of care and skill normally exercised, under similar circumstances, by reputable consultants practicing in this field at this time. No other warranty, expressed or implied, is made as to the professional advice presented in this report.

This report is provided solely for use by HWCP Management Limited and shall not be relied on by any other parties without written approval from BMC.

3 Building Description

3.1 General Overview

The building is located at 18 Kelvin Street, Invercargill, as shown below in Figure 1. The building is a two-storey unreinforced masonry (URM) brick structure tenanted at both ground floor and first floor by Beauty and Beyond.




Figure 1 - Location of 18 Kelvin Street, Invercargill

The building was constructed circa 1910. The shopfront, facing Kelvin St, has full height glazing at ground level. The façade at the first floor has six square windows and a parapet extends above first floor. A shopfront canopy extends the full width of the shopfront. This building has "Tier 2" heritage status in the "Proposed Invercargill City District Plan", dated January 2017. The building description is summarised below in Table 1.

Building Feature	Description
Building address:	18 Kelvin Street, Invercargill
Ground plan footprint dimensions:	20.5 m x 6.6 m
First floor plan dimensions:	17.6 m x 6.6 m
Number of storeys:	2
Gross floor area (approximate):	250 m ²
Building history:	Built circa 1910
Archive plan availability	Fitout alterations plan undertaken in 2003
Occupancy:	Retail
Importance Classification: (AS/NZS 1170.0:2002: Table 3.2)	IL2 Normal building
Heritage Classification:	Tier 2

Table 1: Building Description

3.2 Construction Materials & Configuration

The building plan is rectangular in plan with URM walls around the perimeter. The shopfront is at the east end of the building, facing Kelvin Street. The side walls are on the north and south sides of the building. A 2003 fitout floor plan drawing is shown below in Figure 2.




Figure 2 - Building floor plan at ground floor and first floor

The perimeter side walls and rear wall are full height and constructed of unreinforced masonry (URM), see Figure 3 for an image of the rear of the building. At the shopfront, the ground floor is 'open' with URM wall/piers above. The URM wall/piers are likely supported by a steel beam spanning between URM wall/piers across the shopfront. The canopy is supported by 4 braces attached to the URM piers and spandrel above first floor.



Figure 3 - Rear elevation of building

The roof is constructed of corrugated iron roofing. The roof framing was not visible. It is likely that roofing is supported by timber purlins spanning between timber trusses supported on perimeter URM side walls.

The first floor is constructed from timber planks on timber joists. The joists are supported by the perimeter URM side walls and interior supports. The first floor has a large opening at the central stairwell, as shown below in Figure 4.

The ground floor framing is assumed to be timber framing supported by timber piles. The URM brick walls are assumed to be supported on concrete strip footings.



Figure 4 – First floor at stairwell opening

3.3 Lateral Load Resisting Structural System

The main components of the lateral load resisting system are perimeter URM walls and the timber diaphragms. At the first floor, the diaphragm is the timber floor framing. At roof level, the diaphragm is the timber roof framing and the corrugated iron roof.

The timber diaphragms and in-plane URM walls work together to transfer the seismic loads from each building level down to ground level. At each building level, the diaphragm spans horizontally, like a beam, between its support points – the in-plane URM walls. The diaphragm effectively distributes the seismic loads to the in-plane URM walls. The URM walls transfer the seismic loads to ground level. The lateral bracing system relies on the in-plane shear capacity of URM walls, the strength of the timber diaphragm, and the connection of the timber diaphragm to the URM wall.

For this era and construction type, it was normal for timber floor framing to be supported in "pockets" in the URM wall. With this connection style, there are no positive connections from the timber diaphragm to the URM walls, just the timber floor joist bearing on the URM wall. At the rear of the building, the URM wall is discontinuous from first floor to ground floor. The wall steps out horizontally from first floor to ground floor.

For seismic loads in the east west direction (longitudinal direction), the lateral loads are resisted by the perimeter side walls.

For seismic loads in the north south direction (transverse direction), the lateral loads are resisted by the rear the URM wall and the shopfront URM wall piers. The first-floor rear URM wall does not continue to ground level. The ground level rear URM wall is offset approximately three metres from the first-floor rear wall. This horizontal

offset of URM walls creates a discontinuity in the load path of the lateral load resisting system. The shopfront elevation comprises of large openings creating a potential soft storey.

3.4 Foundations & Geotechnical

There are no obvious signs of significant settlement in foundations or wall cracking. Foundation details are unknown. It is assumed that the URM walls sit on concrete footings.

A 'Desk Top' geotechnical study titled Invercargill CBD Project Stage 1 dated February 2018 by Geosolve Limited (Ref: 171019) has been completed. This study focussed on the likely ground conditions for the Old Government Life & Old Southland Times buildings but does relate generally to the CBD block as a whole.

Key findings from the Geosolve report that are likely to relate to this building assessment are:

- Ground / Soil Class D is to be used for the purposes of seismic assessment.
- Some liquefaction induced differential settlement is likely in a significant (ULS) seismic event.
- Bearing conditions for typical strip footings are less than 'good ground' as defined by NZS3604 (approximately half). Note BMC has not checked actual foundation bearing pressures for this building.

4 Building Inspection

4.1 Documentation

Documentation received by BMC that was considered relevant to this report includes: -

Description	Revision	Issue Date
Fitout alteration drawings By: unknown	D	2003
Invercargill City: Central City Area Heritage Buildings Re-Assessment 2016 By: Dr. Andrea Farminer and Robin Miller	N/A	2016



4.2 Observations and/or Damage

The building was inspected by Andrew Marriott and Charlotte Corston of BMC on 26/02/2018. This was a visual inspection only. The inspection included both the internal and external accessible areas of the building. No invasive investigations were carried out.

Items of structural damage observed:

- Pounding damage
- Cracking in URM along rear elevation

The following photo images and observations and specific comments relate to the inspection. A complete photo record of the inspection is available on request.

No#	Photo	Comments
1	 <p>A photograph of a three-story building with a light-colored facade. The top story has a decorative cornice with the name 'THOMPSON'S' in the center. Below this is a row of five windows with decorative mullions. A white awning extends over the ground floor entrance, featuring the 'Beauty Beyond' logo and the text 'PHONE: 2141262' and 'beautybeyond.co.nz'. A white SUV is parked on the street in front of the building. To the right, a portion of a taller, modern building with a red and yellow facade is visible.</p>	<p>Note there is no seismic gap to the adjacent buildings.</p> <p>The shopfront has a potential soft storey.</p> <p>Adjacent building to the north (Kelvin Hotel) is 8 stories.</p>
2	 <p>A close-up photograph of the corner of a building. A vertical crack is visible in the light-colored masonry wall. To the left, a dark metal staircase with a white-painted railing is visible. A window with a dark frame is located on the right side of the frame. A white downspout runs vertically along the wall. A black horizontal pipe or railing is in the foreground.</p>	<p>Pounding damage observed between 18 Kevin St and the building to the north (Kelvin Hotel)</p>




No#	Photo	Comments
3		Cracking in URM along base of window frames on the rear elevation, showing potential out-of-plane failure of this rear URM wall.
4		Step cracking to top right hand corner of the rear elevation of the building
5		URM wall along the rear elevation is not continuous between ground floor and first floor.

Table 2 – Photos of observations and damage

5 Assessment

5.1 Specific Calculations / Engineering Assessment

In the longitudinal direction (east west direction), the limiting element of the lateral load carrying capacity is the out-of-plane capacity of the URM wall at the shopfront and at the rear of the building. The out-of-plane capacity of this wall was calculated to be approximately 20%NBS (IL2). The shopfront wall was taken as 325mm thick, 8.5 m height (first floor to top of parapet) and supported on double steel beams above the open shopfront. The wall appears to have no positive connection to the timber diaphragm at first floor or at roof level. As such, the wall essentially cantilevers from its support point with little to no lateral support above. See out-of-plane calculation in the Appendix A.

In the transverse direction (north south direction), there is a soft storey critical structural weakness. A soft storey in a building occurs when a significantly more flexible building level supports a more rigid building level. This occurs at the shopfront, where a relatively heavy rigid first floor façade is supported by a “open” ground floor framing with no distinct lateral force resisting elements. At ground level, in the transverse direction, the only lateral load resisting element is the URM wall at the rear of the building.

In addition to the soft storey, the ground floor rear URM walls are offset horizontally to the first-floor rear wall by three metres. This off-set creates another discontinuity in the load path of the lateral load resisting system. The load path requires the timber diaphragm to distribute these loads to the in-plane URM walls. It is believed that the timber diaphragm is connected to the URM walls only by a friction connection. The timber diaphragm has a large opening at the stairwell, which decreases the shear capacity of the diaphragm.

Due to the soft storey critical structural weakness and the horizontal offset of the URM walls, it is estimated that the capacity of the building in the transverse direction is approximately 15-20%NBS (IL2).

5.2 IEP Spreadsheet Calculations

The NZ Society of Earthquake Engineers (NZSEE) has developed an assessment calculation (the IEP Spreadsheet) to be used in a preliminary estimation of the seismic capacity (Percentage of New Build Standard (%NBS)) of a building. This is primarily based on comparing the current seismic design Loadings Code (NZS1170.5) in 2018 with the seismic design load at the time the building was designed. It assumes that the original design was built to at least 100%NBS of the design load at this time. It allows for other ‘engineering judgement’ and observation factors to be incorporated but the process is at best a preliminary estimation.

BMC has carried out an IEP assessment for this building. The results were 15%NBS (IL2). The lateral capacity of the building is limited by the soft storey weakness and the age of the building.

The IEP assessment of this building therefore indicates an overall score of 15%NBS (IL2) corresponding to a ‘Grade E’ building as defined by the New Zealand Society for Earthquake Engineering (NZSEE) building grading scheme. This is below the threshold for earthquake prone buildings (34%NBS) and below the threshold for earthquake risk buildings (67%NBS) as recommended by the NZSEE. The IEP Spreadsheets are (for both parts of the building) included as Appendix A.

6 Seismic Restraint of Non-Structural Items

During an earthquake, the safety of people can be put at risk due to non-structural items falling on them. These items should be adequately seismically restrained, where possible, to the NZS 4219:2009 "The Seismic Performance of Engineering Systems in Buildings".

An assessment has not been made of the bracing of the false ceilings, in-ceiling ducting, services and plant or contents. These issues are outside the scope of this initial assessment but could be the subject of another investigation. False (or suspended) ceilings exist on both ground and first floor levels of this building.

7 Continued Occupancy Recommendations

Based on our assessment of the building, BMC considers continued occupancy is appropriate for 6-12 months *subject to the conditions of the Building (Earthquake-prone buildings) Amendment Act 2016*.

If required, a Detailed Seismic Assessment (DSA) or a more detailed assessment could be carried out with intrusive investigation work into the nature and capacity of the timber framing connections to the front and rear URM walls at the roof and first floor level. This more detailed assessment could enable an understanding of other aspects of its seismic performance and potentially raise the lateral capacity of the building to above 34%NBS.

8 Conclusions

Based on our assessment, the building has a seismic load carrying capacity of less than 34%NBS and the building, therefore, is considered to be potentially Earthquake Prone as defined by the Building Act.

This building has "Tier 2" heritage status in the "Proposed Invercargill City District Plan", dated January 2017.

If a more defined level of performance is required, then a DSA would need to be carried out.

For more summary comments, refer to the Executive Summary.

APPENDIX A - NZSEE IEP Spreadsheet & Out-of-Plane Wall Calculation

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}**Page 1**

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in the "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-1 Initial Evaluation Procedure Step 1**Step 1 - General Information****1.1 Photos (attach sufficient to describe building)**


See ISA report



NOTE: THERE ARE MORE PHOTOS ON PAGE 1a ATTACHED

1.2 Sketches (plans etc, show items of interest)

See ISA report



NOTE: THERE ARE MORE SKETCHES ON PAGE 1a ATTACHED

1.3 List relevant features (Note: only 10 lines of text will print in this box. If further text required use Page 1a)

See ISA report

1.4 Note information sources

Tick as appropriate

Visual Inspection of Exterior
Visual Inspection of Interior
Drawings (note type)

<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>
<input checked="" type="checkbox"/>

Specifications
Geotechnical Reports
Other (list)

<input type="checkbox"/>
<input checked="" type="checkbox"/>
<input type="checkbox"/>

2003 Fitour alteration drawings

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 2

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-2 Initial Evaluation Procedure Step 2

Step 2 - Determination of (%NBS)_b

(Baseline (%NBS) for particular building - refer Section B5)

2.1 Determine nominal (%NBS) = (%NBS)_{nom}

a) Building Strengthening Data

Tick if building is known to have been strengthened in this direction

If strengthened, enter percentage of code the building has been strengthened to

Longitudinal

☐

N/A

Transverse

☐

N/A

b) Year of Design/Strengthening, Building Type and Seismic Zone

- Pre 1935 ☒
- 1935-1965 ☐
- 1965-1976 ☐
- 1976-1984 ☐
- 1984-1992 ☐
- 1992-2004 ☐
- 2004-2011 ☐
- Post Aug 2011 ☐

- Pre 1935 ☒
- 1935-1965 ☐
- 1965-1976 ☐
- 1976-1984 ☐
- 1984-1992 ☐
- 1992-2004 ☐
- 2004-2011 ☐
- Post Aug 2011 ☐

Building Type: Others

Others

Seismic Zone: Not applicable

Not applicable

c) Soil Type

From NZS1170.5:2004, Cl 3.1.3 :

D Soft Soil

D Soft Soil

From NZS4203:1992, Cl 4.6.2.2 :
(for 1992 to 2004 and only if known)

Not applicable

Not applicable

d) Estimate Period, T

Comment:

$h_n = 8.5$

$A_c = 1.00$

8.5 m

1.00 m²

- Moment Resisting Concrete Frames: $T = \max(0.09h_n^{0.75}, 0.4)$ ☐
- Moment Resisting Steel Frames: $T = \max(0.14h_n^{0.75}, 0.4)$ ☐
- Eccentrically Braced Steel Frames: $T = \max(0.08h_n^{0.75}, 0.4)$ ☐
- All Other Frame Structures: $T = \max(0.06h_n^{0.75}, 0.4)$ ☐
- Concrete Shear Walls: $T = \max(0.09h_n^{0.75}/A_c^{0.5}, 0.4)$ ☐
- Masonry Shear Walls: $T \leq 0.4\text{sec}$ ☒
- User Defined (input Period): ☐

- ☐
- ☐
- ☐
- ☐
- ☐
- ☒
- ☐

Where h_n = height in metres from the base of the structure to the uppermost seismic weight or mass.

T: 0.40

0.40

e) Factor A: Strengthening factor determined using result from (a) above (set to 1.0 if not strengthened)

Factor A: 1.00

1.00

f) Factor B: Determined from NZSEE Guidelines Figure 3A.1 using results (a) to (e) above

Factor B: 0.03

0.03

g) Factor C: For reinforced concrete buildings designed between 1976-84 Factor C = 1.2, otherwise take as 1.0.

Factor C: 1.00

1.00

h) Factor D: For buildings designed prior to 1935 Factor D = 0.8 except for Wellington and Napier (1931-1935) where Factor D may be taken as 1.0, otherwise take as 1.0.

Factor D: 0.80

0.80

(%NBS)_{nom} = AxBxCxD(%NBS)_{nom} 2%

2%

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 3

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-2 Initial Evaluation Procedure Step 2 continued

2.2 Near Fault Scaling Factor, Factor E

If $T \leq 1.5\text{sec}$, Factor E = 1a) Near Fault Factor, $N(T,D)$

(from NZS1170.5:2004, Cl 3.1.6)

Longitudinal

N(T,D): 1

Transverse

1

b) Factor E

= $1/N(T,D)$

Factor E: 1.00

1.00

2.3 Hazard Scaling Factor, Factor F

a) Hazard Factor, Z, for site

Location: Invercargill

Refer right for user-defined locations

Z = 0.17 (from NZS1170.5:2004, Table 3.3)

 Z_{1992} = 0.68 (NZS4203:1992 Zone Factor from accompanying Figure 3.5(b)) Z_{2004} = 0.17 (from NZS1170.5:2004, Table 3.3)

b) Factor F

For pre 1992 = $1/Z$ For 1992-2011 = Z_{1992}/Z For post 2011 = Z_{2004}/Z

Factor F: 5.88

5.88

2.4 Return Period Scaling Factor, Factor G

a) Design Importance Level, I

(Set to 1 if not known. For buildings designed prior to 1965 and known to be designed as a public building set to 1.25. For buildings designed 1965-1976 and known to be designed as a public building set to 1.33 for Zone A or 1.2 for Zone B. For 1976-1984 set I value.)

I = 1

1

b) Design Risk Factor, R_o

(set to 1.0 if other than 1976-2004, or not known)

 R_o = 1

1

c) Return Period Factor, R

(from NZS1170.0:2004 Building Importance Level)

Choose Importance Level

☐ 1 ☒ 2 ☐ 3 ☐ 4☐ 1 ☒ 2 ☐ 3 ☐ 4

R = 1.0

1.0

d) Factor G

= IR_o/R

Factor G: 1.00

1.00

2.5 Ductility Scaling Factor, Factor H

a) Available Displacement Ductility Within Existing Structure

Comment:

URM Shear Walls

 μ = 1.25

1.25

b) Factor H

For pre 1976 (maximum of 2)

For 1976 onwards

= k_{μ}
= 1.14
= 1

Factor H: 1.14

 k_{μ}
1.14
1
1.14(where k_{μ} is NZS1170.5:2004 Inelastic Spectrum Scaling Factor, from accompanying Table 3.3)

2.6 Structural Performance Scaling Factor, Factor I

a) Structural Performance Factor, S_p

(from accompanying Figure 3.4)

Tick if light timber-framed construction in this direction

☐
 S_p = 0.93☐
0.93

b) Structural Performance Scaling Factor

= $1/S_p$

Factor I: 1.08

1.08

Note Factor B values for 1992 to 2004 have been multiplied by 0.67 to account for S_p in this period2.7 Baseline %NBS for Building, (%NBS)_b(equals (%NBS)_{nom} x E x F x G x H x I)

17%

17%

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 4

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-3 Initial Evaluation Procedure Step 3

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

a) Longitudinal Direction

potential CSWs	Effect on Structural Performance (Choose a value - Do not interpolate)	Factors
3.1 Plan Irregularity		
Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant		Factor A <input type="text" value="1.0"/>
Comment		
3.2 Vertical Irregularity		
Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant		Factor B <input type="text" value="1.0"/>
Comment		
3.3 Short Columns		
Effect on Structural Performance <input type="radio"/> Severe <input type="radio"/> Significant <input checked="" type="radio"/> Insignificant		Factor C <input type="text" value="1.0"/>
Comment		
3.4 Pounding Potential		
(Estimate D1 and D2 and set D = the lower of the two, or 1.0 if no potential for pounding, or consequences are considered to be minimal)		

a) Factor D1: - Pounding Effect

Note:
Values given assume the building has a frame structure. For stiff buildings (eg shear walls), the effect of pounding may be reduced by taking the coefficient to the right of the value applicable to frame buildings.

Factor D1 For Longitudinal Direction:				1.0
Table for Selection of Factor D1		Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Separation				
Alignment of Floors within 20% of Storey Height		<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1
Alignment of Floors not within 20% of Storey Height		<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8
Comment				

b) Factor D2: - Height Difference Effect

Factor D2 For Longitudinal Direction:				1.0
Table for Selection of Factor D2		Severe 0<Sep<.005H	Significant .005<Sep<.01H	Insignificant Sep>.01H
Height Difference > 4 Storeys	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1	
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1	
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input checked="" type="radio"/> 1	
Comment				

Factor D

3.5 Site Characteristics - Stability, landslide threat, liquefaction etc as it affects the structural performance from a life-safety perspective

Effect on Structural Performance ☐ Severe ☐ Significant ☒ Insignificant

Factor E

Comment

3.6 Other Factors - for allowance of all other relevant characteristics of the building

For ≤ 3 storeys - Maximum value 2.5
otherwise - Maximum value 1.5.
No minimum.

Factor F

Record rationale for choice of Factor F:

Comment

3.7 Performance Achievement Ratio (PAR)
(equals A x B x C x D x E x F)

PAR
Longitudinal

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 5

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-3 Initial Evaluation Procedure Step 3

Step 3 - Assessment of Performance Achievement Ratio (PAR)

(Refer Appendix B - Section B3.2)

b) Transverse Direction

Factors

potential CSWs

Effect on Structural Performance
(Choose a value - Do not interpolate)

3.1 Plan Irregularity

Effect on Structural Performance ☐ Severe☒ Significant☐ InsignificantFactor A

Horizontal step - Rear wall steps

3.2 Vertical Irregularity

Effect on Structural Performance ☐ Severe☒ Significant☐ InsignificantFactor B

Soft Storey

3.3 Short Columns

Effect on Structural Performance ☐ Severe☐ Significant☒ InsignificantFactor C

Comment

3.4 Pounding Potential

(Estimate D1 and D2 and set D = the lower of the two, or 1.0 if no potential for pounding, or consequences are considered to be minimal)

a) Factor D1: - Pounding Effect

Note:

Values given assume the building has a frame structure. For stiff buildings (eg shear walls), the effect of pounding may be reduced by taking the coefficient to the right of the value applicable to frame buildings.

Factor D1 For Transverse Direction:

Table for Selection of Factor D1	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Alignment of Floors within 20% of Storey Height	<input checked="" type="radio"/> 1	<input type="radio"/> 1	<input type="radio"/> 1
Alignment of Floors not within 20% of Storey Height	<input type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 0.8

Comment

b) Factor D2: - Height Difference Effect

Factor D2 For Transverse Direction:

Table for Selection of Factor D2	Severe	Significant	Insignificant
	0<Sep<.005H	.005<Sep<.01H	Sep>.01H
Height Difference > 4 Storeys	<input checked="" type="radio"/> 0.4	<input type="radio"/> 0.7	<input type="radio"/> 1
Height Difference 2 to 4 Storeys	<input type="radio"/> 0.7	<input type="radio"/> 0.9	<input type="radio"/> 1
Height Difference < 2 Storeys	<input type="radio"/> 1	<input type="radio"/> 1	<input type="radio"/> 1

Comment

Factor D

3.5 Site Characteristics - Stability, landslide threat, liquefaction etc as it affects the structural performance from a life-safety perspective

Effect on Structural Performance ☐ Severe☐ Significant☒ InsignificantFactor E

Comment

3.6 Other Factors - for allowance of all other relevant characteristics of the building

For ≤ 3 storeys - Maximum value 2.5
otherwise - Maximum value 1.5.
No minimum.Factor F

Record rationale for choice of Factor F:

Comment

3.7 Performance Achievement Ratio (PAR)
(equals A x B x C x D x E x F)PAR
Transverse

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 6

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-4 Initial Evaluation Procedure Steps 4, 5, 6 and 7

Step 4 - Percentage of New Building Standard (%NBS)

	Longitudinal	Transverse
4.1 Assessed Baseline %NBS (%NBS) _b (from Table IEP - 1)	17%	17%
4.2 Performance Achievement Ratio (PAR) (from Table IEP - 2)	1.00	0.20
4.3 PAR x Baseline (%NBS) _b	15%	15%
4.4 Percentage New Building Standard (%NBS) - Seismic Rating (Use lower of two values from Step 4.3)		15%

Step 5 - Is %NBS < 34?

YES

Step 6 - Potentially Earthquake Risk (is %NBS < 67)?

YES

Step 7 - Provisional Grading for Seismic Risk based on IEP

Seismic Grade E

Additional Comments (items of note affecting IEP based seismic rating)

Relationship between Grade and %NBS:

Grade:	A+	A	B	C	D	E
%NBS:	> 100	100 to 80	79 to 67	66 to 34	< 34 to 20	< 20

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 7

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-5 Initial Evaluation Procedure Step 8

Step 8 - Identification of potential Severe Structural Weaknesses (SSWs) that could result in significant risk to a significant number of occupants

8.1 Number of storeys above ground level

2

8.2 Presence of heavy concrete floors and/or concrete roof? (Y/N)

N

Potential Severe Structural Weaknesses (SSWs):

Note: Options that are greyed out are not applicable and need not be considered.

Occupancy not considered to be significant - no further consideration required•

Risk not considered to be significant - no further consideration required•

The following potential Severe Structural Weaknesses (SSWs) have been identified in the building that could result in significant risk to a significant number of occupants:

1. None identified
2. Weak or soft storey (except top storey)
3. Brittle columns and/or beam-column joints the deformations of which are not constrained by other structural elements
4. Flat slab buildings with lateral capacity reliant on low ductility slab-to-column connections
5. No identifiable connection between primary structure and diaphragms
6. Ledge and gap stairs

IEP Assessment Confirmed by



Signature

Andrew Marriott

Name

72638

CPEng. No

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out in "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Initial Evaluation Procedure (IEP) Assessment - Completed for {Client/TA}

Page 1a

Street Number & Name:	18 Kelvin St	Job No.:	1711-2266
AKA:		By:	Charlotte Corston
Name of building:	Beauty and Beyond	Date:	9/04/2018
City:	Invercargill	Revision No.:	

Table IEP-1a Additional Photos and Sketches

Add any additional photographs, notes or sketches required below:

Note: print this page separately

WARNING!! This initial evaluation has been carried out solely as an initial seismic assessment of the building following the procedure set out "The Seismic Assessment of Existing Buildings" Technical Guidelines for Engineering Assessments, July 2017. This spreadsheet must be read in conjunction with the limitations set out in the accompanying report, and should not be relied on by any party for any other purpose. Detailed inspections and engineering calculations, or engineering judgements based on them, have not been undertaken, and these may lead to a different result or seismic grade.

Subject:

URM wall out of plane capacity check of shopfront elevation

URM Wall Properties

γ_{wall}	18	kN/m ³
$t_{w\ nom}$	0.325	m
$t_{w\ eff}$	0.319	m
$Q_{Cladding}$	0	kPa
h	5	m
W	29.3	kN
e_b	0.109	m
y_b	2.50	m
γ	1.49	participation
T_p	1.81	sec
Δ_i	0.22	m
Δ_m	0.07	m
D_{ph}	0.34	m
%NBS	19	%

Anchorage Design

C_m	0.06	g
$C_{con}(0.75)$	0.06	g
F^*_{top}	1.9	kN

NZS 1170.5 (2004) parameters

Soil Class	D	
$C_h(0)$	1.12	From Table 3.1, use values in brackets
$N(T,D)$	1	Refer to Section 3.1.6
Z	0.17	Refer to Section 3.1.4
R	1	Refer to Section 3.1.5
$C(0)$	0.19	
R_p	1	From Table 8.1
h_n	8.5	m (Total Height)
h_i	6	m (Average height of part)
C_{Hi}	2.00	
$C_{hc}(T_p)$	0.75	
$C_p(T_p)$	0.28	

Case	Applicable	C_{Hi}
$h_i < 12\ m$	YES	2
$h_i < 0.2h_n$	NO	N/A
$h_i \geq 0.2h_n$	YES	3

$C_p(0.75)$

$C_{hc}(0.75)$	1.48	g
$C_p(0.75)$	1.10	g




Figure 10B.3: Single cantilever