

Built Heritage Fund

- Projects valued up to \$20,000 are eligible to receive maximum 80% funding.
- Projects valued over \$20,000 are eligible to receive maximum 50% funding.

Building Address	Scope of Work	Total Cost of Work	Funding Allocation
7 Clyde Street	Façade painting and entrance door canopy	\$11,663.55	\$9,330.00
30-32 Dee Street	Repainting and scaffolding of front façade, signage replacement, repairs to existing façade lighting and replacement of three glass panes in canopy	\$73,472.93	\$36,735.00
43-45 Dee Street	Verandah lighting and repairs, reinstatement of four transom windows, and front façade lighting	\$41,625.18	\$20,810.00
Grand Hotel and Accommodation 76-86 Dee Street	Façade painting overage	\$9,250.00	\$7,400.00
(Former) Briscoes Building 104-106 Dee Street	Roof weatherproofing and interior plumbing	\$20,000.00	\$16,000.00
(Former) Embassy Theatre 110-122 Dee Street	Replace Spey Street fire escape, cap 60m parapet wall, electrical work along Dee Street frontage, downpipe and rain head replacements, renovation of theatre entrance, façade cleaning and plaster repairs	\$20,000.00	\$16,000.00
Hanan Building 124-130 Dee Street	Façade repainting (inc. scaffolding).	\$20,000.00	\$16,000.00
Blackham Building 136-144 Dee Street	Emergency lighting (interior and exterior)	\$10,819.82	\$8,655.00
155 Dee Street	Replacement of three timber windows, verandah repairs, plaster repairs, and façade repainting	\$42,000.00	\$21,000.00
Invercargill Club 32 Don Street	Refurbishment of first storey stairwell ceiling and fencing project overage	\$19,522.91	\$14,180.00
28 Esk Street	Façade painting and window refurbishment overage (approved last year, but delayed due to street upgrade work)	\$10,400.00	\$5,200.00
34 Esk Street	Relocation of heat pump off façade, replacement of four timber windows, and associated paintwork	\$20,000.00	\$13,495.00
38 Esk Street	Painting overage (approved last year, but delayed due to street upgrade work)	\$8,503.40	\$6,800.00

62 Esk Street	Verandah repairs and painting overage (approved last year, but delayed due to street upgrade work)	\$12,975.00	\$10,380.00
72 Esk Street	Façade painting and scaffolding, and patterned window treatment	\$15,345.00	\$12,275.00
43 Tay Street	Roofing and tray replacement, verandah repair, and verandah painting	\$20,000.00	\$16,000.00
53 Tay Street	Verandah repairs	\$12,620.00	\$10,100.00
(Former) Craig's Printing Building 67 Tay Street	Heat pump installation and film treatment for east windows	\$12,048.05	\$9,640.00
TOTAL			\$250,000.00

Seismic Strengthening Fund

- *Seismic reporting projects are eligible to receive up to 50% of professional advice costs to a maximum grant of \$10,000.*
- *Strengthening works projects are eligible to receive up to 50% of professional advice costs to a maximum grant of \$50,000.*

Building Address	Category	Total Cost of Work	Funding Allocation
43-45 Dee Street	Professional advice: detailed seismic strengthening design	\$17,500.00	\$8,750.00
169-171A Dee Street	Professional advice: detailed seismic strengthening design	\$18,500.00	\$9,250.00
Tudor House 36 Don Street	Professional advice and strengthening works: detailed seismic strengthening design and physical strengthening works	\$232,300.00	\$29,355.00
42 Kelvin Street	Professional advice: detailed seismic strengthening design	\$5,297.50	\$2,645.00
TOTAL			\$50,000.00